

CORDLESS LED FLASHLIGHT ML106/DML808

REPAIR MANUAL




1 CONTENTS


1	CONTENTS	2
2	Cautions for assembling Zoom mechanism.....	3

2 Cautions for assembling Zoom mechanism

Fig. 1




- 1 Pass LED PCBA assembly through Metal focusing ring.



- 2 Align 3 portions of end faces of LED PCBA assembly and end face of Metal focusing ring.

Fig. 3



- 3 Pull out Lead wire of LED PCBA assembly through the hole of AL head body assembly as shown above.